

**The Appendix is an integral part of
Certificate of Accreditation No.: 263/2023 of 31/05/2023**

Accredited entity according to ČSN EN ISO/IEC 17020:2012:

SGS Czech Republic, s.r.o.
CAB number 4067 Inspection Body - Asbestos
K Hájům 1233/2, Stodůlky, 155 00 Praha 5

Ordinal number	Inspection field	Inspection type and scope	Procedure identification	Degree of freedom¹
1.	Detection of presence of asbestos and/or other dangerous fibres including sampling and risk analysis	Construction/technical survey including risk analysis and sampling, focused on the detection of the extent of presence of asbestos and/or other dangerous fibres executed in indoor and outdoor environment	VIP_1 (18.4.2023)	-
2.	Supervision of abatement of asbestos and/or other dangerous fibres including sampling and assessment of efficiency of abatement	Supervision/inspection of process of abatement of asbestos and/or other dangerous fibres including sampling and assessment of abatement efficiency (independent inspection by third party of process and terminations of abatement) executed in indoor and outdoor environment	VIP_2 (18.4.2023)	-

¹ The Certification Body does not apply a flexible approach to the scope of accreditation