

**The Appendix is an integral part of
Certificate of Accreditation No. 311/2023 of 15/06/2023**

Accredited entity according to ČSN EN ISO/IEC 17020:2012:

AmpluServis, a.s.
CAB number 4047 Inspection Body
Ostrava – Třebovice, ul. Elektrárenská 5558, 709 74

Ordinal number	Inspection field	Inspection type and scope	Inspection procedure	Degree of freedom ¹
1.	Inspection of stated pressure equipment – boilers	Assessment of documentation, inspection of new and operated equipment	IP-Kotle-01 of 01/05/2023	-
2.	Inspection of stated pressure equipment – TNS	Assessment of documentation, inspection of new and operated equipment	IP-TNS-01 of 01/05/2023	-
3.	Inspection of rotating machines – vibration	Assessment of documentation, inspection of new and operated equipment	IP-VD-01 of 27/01/2015	-
4.	Inspection of pressure devices – technical inspection of low-pressure boiler house	Assessment of documentation, inspection of new and operated equipment	IP-OPNTK-01 of 16/01/2017	-
5.	Inspection of dedicated gas equipment – regulation stations, industrial gas lines, equipment for the consumption of gas by combustion	Assessment of documentation, inspection of new and operated equipment	IP-Plyn-01 of 01/05/2023	-
6.	Inspection of welding	Inspection of welding procedures in repair, erection of new and operated equipment	IP-SV-01 of 03/02/2022	-

¹ The Certification Body does not apply a flexible approach to the scope of accreditation

IP	Inspection procedure
TNS	Stationary pressure vessel
VD	Vibration diagnostics
OPNTK	Professional inspection of low-pressure boiler house
SV	Welding